

Oil Field Environmental Incident Summary

Incident: 20150731090314 **Date/Time of Notice:** 07/31/2015 09:03

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MADISON 1-28H

Field Name: DOLLAR JOE

Well File #: 20791

Date Incident: 7/30/2015 **Time Incident:** 16:30

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 97

Sec: 28

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Don Leiseth
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

20 ft. by 8 ft. area inside and outside of the berm.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Fluid will be sucked out and contaminated material will be removed, replacing it with clean fill. A new valve will be installed.

Wastes Disposal Location: R360

Agencies Involved: Called John Rumppe @ 9:00 a.m. on 7/31/2015

Updates

Date: 7/31/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release was contained within and E&P Well pad. Oil & Gas retains jurisdiction.